This Professional PenLite is for general, NON-CONTACT illumination only.

Diagnostic Menu

WARNING: Do not use for transillumination as burns could result. This instrument is not to be used in the presence of flammable anesthetics.

PARTS OF THE PROFESSIONAL PENLITE:

CHANGING THE LAMP:

1. Unscrew lamp/tip assembly. Discard. Replace with Welch Allyn #07600 lamp/tip assembly.

CHANGING BATTERIES:

1. Unscrew lamp/tip assembly and remove old batteries.
2. Insert new AAA batteries (may be inserted either way). For best light output and battery life use alkaline batteries.
3. Replace lamp/tip assembly.

WARRANTY:

Welch Allyn guarantees the PenLite, with the exception of lamps and batteries against all manufacturing defects. Welch Allyn will repair or replace free of charge any parts of its own manufacture proven to be defective through causes other than misuse, neglect, damage in shipment or normal wear.

Welch Allyn®
Welch Allyn, Inc.
4341 State St. Rd
PO Box 220
Skaneateles Falls. NY 13153-0220
(315) 685-4560

NO. 766111